



EXISTING PROBLEM AREAS



LEGEND	
	BELOW LEVEL OF SERVICE STANDARDS
	SIGNAL WARRANTS MET
	ACCIDENT RATE ABOVE STATE AVERAGE
DEFICIENCIES	
	SIGHT DISTANCE
	ADVANCE SIGNING
	GEOMETRY
	LACK OF TURN LANES 16800 FT

JULY 2001