



EXISTING PROBLEM AREAS



LEGEND

- BELOW LEVEL OF SERVICE STANDARDS
- ⊕ SIGNAL WARRANTS MET
- ACCIDENT RATE ABOVE STATE AVERAGE
- DEFICIENCIES
- 👁 SIGHT DISTANCE
- ◆ ADVANCE SIGNING
- ▽ GEOMETRY
- ↩ LACK OF TURN LANES 16800 FT

JULY 2001